

Harsh 5-4 Downshift on Deceleration

Service

Category Drivetrain

Section Automatic Transmission/Transaxle

Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION	
2006 – 2009	Camry	Body Type(s): 4Dr. Sedan Drive Type(s): 2WD Engine(s): 2AZ Plant Code(s): 3, R, U Transmission(s): 5AT VDS(s): BE32K, BE46K WMI(s): 4T1, 4T4, JTN	

TSB SUPERSESSION NOTICE

The information contained in this TSB supersedes TSB No. TC010-06.

- Production Change Information has been updated with new VIN information.
- . Applicability has been updated to include 2008 and 2009 model year Camry.

TSB No. TC010-06 is Obsolete and any printed versions should be discarded. Be sure to review the entire content of this service bulletin before proceeding.

Introduction

Some 2006 – 2009 model year Camry vehicles equipped with the 2AZ-FE engine and U250E automatic transaxle (ATM) may exhibit a harsh 5–4 downshift under the following conditions:

- ATM at normal operating temperature
- After driving above 45 mph (72 km/h)
- Decelerating through 28 mph (45 km/h)

The line pressure control solenoid assembly (SLT) has been improved to reduce this condition on customer complaint vehicles.

TOYOTA T-SB-0033-08 April 15, 2008 Page 2 of 3

Harsh 5-4 Downshift on Deceleration

Production Change Information

This TSB applies to vehicles produced BEFORE the Production Change Effective VINs shown below.

MODEL	ENGINE	PLANT	PRODUCTION CHANGE EFFECTIVE VIN
Camry	2AZ-FE	Tsutsumi	JTNBE46K#83146849
		ТММК	4T1BE46K#9U267985
			4T1BE46K#9U797632
		SIA	4T4BE46K#8R037795

Warranty Information

OP CODE	DESCRIPTION	MY	TIME	OFP	T1	T2
369401	R & R Transaxle Solenoid Assembly	2006	1.6	35290-33030 35290-45010	26	88
		2007	1.9			
		2008				
		2009				

APPLICABLE WARRANTY

- This repair is covered under the Toyota Powertrain Warranty. This warranty is in effect for 60 months or 60,000 miles, whichever occurs first, from the vehicles in-service date.
- Warranty application is limited to correction of a problem based upon a customers specific complaint.

Parts Information

MODEL YEAR	PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
2006 – 2007	35290-33030	35290-45010	Solenoid Assembly,	1
2008 – 2009	35290-45010	Same	Line Pressure Control	1
All	35168-21020	Same	Gasket, Automatic Transaxle Oil Pan	1

Required Tools & Equipment

TOOLS & MATERIAL	QUANTITY	
Toyota Genuine Adhesive 1344, Three Bond 1344, or equivalent	As Needed	
Automatic Transmission Fluid (ATF), Toyota Genuine ATF WS	3.5 liters (3.7 U.S. qts, 3.1 Imp. qts)	

TOYOTA T-SB-0033-08 April 15, 2008 Page 3 of 3

Harsh 5-4 Downshift on Deceleration

Repair Procedure

- 1. Test drive and verify that the 5–4 harsh downshift condition occurs as described in the Introduction section in this TSB.
- 2. Replace the SLT solenoid assembly.

Refer to the Technical Information System (TIS):

• 2006 model year Camry Repair Manual:

<u>Drivetrain – Automatic Transmission/Transaxle – "Transmission Valve Body Assy (U250E):</u> Replacement"

• 2007 model year Camry Repair Manual:

Drivetrain – Automatic Transmission/Transaxle: Unit Repair – "U250E Automatic Transaxle: Shift Solenoid Valve: Removal, Disassembly, Inspection, Reassembly"

2008 model year Camry Repair Manual:

Drivetrain – Automatic Transmission/Transaxle: Unit Repair – "U250E Automatic Transaxle: Shift Solenoid Valve: Removal, Disassembly, Inspection, Reassembly"

• 2009 model year Camry Repair Manual:

Drivetrain – Automatic Transmission/Transaxle: Unit Repair – "U250E Automatic Transaxle: Shift Solenoid Valve: Removal, Disassembly, Inspection, Reassembly"

NOTE

For SLT solenoid identification, refer to TSB No. <u>TC007-05</u>, "U250E Transmission Solenoid Identification".

3. Reinstall the automatic transaxle oil pan.

Refer to TIS:

2006 model year Camry Repair Manual:

<u>Drivetrain – Automatic Transmission/Transaxle – "Transmission Valve Body Assy (U250E):</u> Replacement"

2007 / 2008 / 2009 model year Camry Repair Manual:

Drivetrain – Automatic Transmission/Transaxle: Unit Repair – "U250E Automatic Transaxle: Shift Solenoid Valve: Installation"

4. Test drive and verify that the ATM operates normally.